

39360 3rd St. E., Ste. 301
 Palmdale, Ca. 93550-3255
 Local Phone: 661-947-8485
 Toll Free: 800-962-6976

ACCESSORY SIZING SHEET

Rotary Converter Model	Time-Delay Fuse	Three-Phase Fusible Switch Disconnect
CNC PAC-1	10 AMP (\$9.50 EA.)	30 AMP (\$75.00)
CNC PAC-2	10 AMP (\$9.50 EA.)	30 AMP (\$75.00)
CNC PAC-3	15 AMP (\$11.10 EA.)	30 AMP (\$75.00)
CNC PAC-5	30 AMP (\$11.10 EA.)	30 AMP (\$75.00)
CNC PAC-7	40 AMP (\$15.00 EA.)	60 AMP (\$104.69)
CNC PAC-10	45 AMP (\$15.00 EA.)	60 AMP (\$104.69)
CNC PAC-15	60 AMP (\$17.00 EA.) Extensions (\$40.00 EA.)	100 AMP (\$202.50)
CNC PAC-20	80 AMP (\$25.00 EA.) Extensions (\$53.50 EA.)	200 AMP (\$438.44)
CNC PAC-25	100 AMP (\$29.10 EA.) Extensions (\$53.50 EA.)	200 AMP (\$438.44)
CNC PAC-30	125 AMP (\$46.80 EA.)	200 AMP (\$438.44)
CNC PAC-40	150 AMP (\$55.00 EA.)	400 AMP *
CNC PAC-50	200 AMP *	400 AMP *
CNC PAC-75	300 AMP *	400 AMP *
CNC PAC-100	375 AMP *	600 AMP *

*** NOT NORMALLY STOCKED, CALL FOR PRICING AND AVAILABILITY**

-THREE FUSES (AND EXTENSIONS WHERE APPLICABLE) NEEDED FOR EACH ROTARY CONVERTER SETUP

-ALL ACCESSORIES ARE NON-RETURNABLE

-ALL ABOVE SIZING FOR R SERIES CONVERTERS ONLY